

Bibury Street Sign Audit (July 2021)









Photo	Sign	Location	Condition & Recommendation
	Restricted Byway	The Pike B4425	Needs Uprighting
	Finger Post	The Pike B4425	Slight damage. Cleaning required.
	7.5 T weight limit. Accept for Access	The Pike B4425	Re-align
	7.5 T weight limit. Accept for Access	The Pike B4425	Re-align
	Weight limit 17 tonnes at Swan Bridge	The Pike B4425	Post rotten. Replace post
	Fosse Cross Chedworth	The Pike B4425	Rotten, new sign and re-align
	Fosse Cross Chedworth	The Pike B4425	Rotten, new sign and re-align
	Give Way	The Pike B4425	Obscured by hedge. Relocate and re-align.









Photo	Sign	Location	Condition & Recommendation
	New Gateway	The Pike B4425	Obscured by trees
	Junction	The Pike B4425	Good
	40	Approaching The Pike	Good
	40	Approaching the village from Barnsley	Good. Require cleaning
	40	Approaching the village from Barnsley	Good. Require cleaning
	30	Approaching the village from Barnsley	Good. Require cleaning
	30	Approaching the village from Barnsley	Good. Require cleaning
	30	Approaching the village from Barnsley	Good. Require cleaning









Photo	Sign	Location	Condition & Recommendation
	40	Approaching the village from Barnsley	Good. Require cleaning
	Public Footpath	By 'Rozzers'	Good
	Public Footpath	'The Batfield'	Replace
	Public Footpath	The Batfield'	Replace
	Ablington Footpath	Before Arlington Farm	Poor condition. Not visible. Faded. Replace & Re-locate.
	Ablington Footpath	Before Arlington Farm	Poor condition. Not visible. Faded. Replace & Re-locate.
	No Through Road	Opposite Long Cottage & The Old Manse	Faded. Replace
	Access to residents. Baptist Church.	Arlington Green	Re-align








Photo	Sign	Location	Condition & Recommendation
	No Entry	Arlington Green	Good
	Post with no sign	Arlington Green	Remove
	Access to residents.	Arlington Green	Good
	Access to residents. Baptist Church.	Arlington Green	Good. Requires re-aligning.
	Multiple signs	Hawkers Hill	Re-think. Fewer signs.
	17 T	Swan Bridge	Very dirty. Clean or replace
	17 T	Swan Bridge	Very dirty. Clean or replace
	Use Footbridge	Swan Bridge	Very dirty. Clean









Photo	Sign	Location	Condition & Recommendation
	Sign post - 3 way	Swan Bridge	Very dirty. Clean or replace
	Sign post - 3 way	Swan Bridge	Very dirty. Clean or replace
	Use Footbridge	Swan Bridge	Very dirty. Clean
	Bends for 400 yds	The Street	Question relevance. Remove?
	No Entry	Church Road/The Street	Requires cleaning. Too high? Improve visibility.
	No Entry	Church Road/The Street	Requires cleaning. Too high? Improve visibility.
	No Entry	Church Road/The Street	Requires cleaning. Too high? Improve visibility.
	Bollards with reflective discs	Church Road/The Street	Replace as no longer reflective. Some missing replace all.

Photo	Sign	Location	Condition & Recommendation
	Bollards with reflective discs	Church Road/The Street	Replace as no longer reflective. Some missing replace all.
	Church School Village Hall	Cemetery Lane	Re-locate to main road. Make 2 sided for improved visibility.
	No Through Road	Packhorse Lane	Good. Obscured by plants
	Fire Hydrant	Packhorse Lane	Replace
	Fire Hydrant	Packhorse Lane	Replace
	Finger Post	Main road B4425	Good
	Finger Post	Main road B4425	Good
	Give Way. Risk of sliding 400yds	Coln Road/B4425	Replace with bend sign.









Photo	Sign	Location	Condition & Recommendation
	Risk of sliding 400 yds	Approaching village from Football Ground	Relevance?
	30	Approaching village from Football Ground	Obscured by overgrowth
	30	Approaching village from Football Ground	Obscured by overgrowth
	40	Approaching village from Football Ground	Obscured by overgrowth
	40	Approaching village from Football Ground	Obscured by overgrowth
	Bend 40	Approaching village from Football Ground	Good. Requires cleaning no longer reflective
	Junction 40	Aldsworth Road	Good
	Concealed Entrance	Football Ground	Good. requires cleaning.









Photo	Sign	Location	Condition & Recommendation
	10% gradient	Football Ground	Very poor condition. Replace
	10% gradient	Football Ground	Very poor condition. Replace
	40/Open limit	Coln Road opposite Bibury Mill access road	Damaged. Requires cleaning. Not visible to cars.
	40/Open limit	Coln Road opposite Bibury Mill access road	Damaged. Requires cleaning. Not visible to cars.
	40/Open limit	Coln Road opposite Bibury Mill access road	Damaged. Requires cleaning. Not visible to cars.
	40/Open limit	Coln Road opposite Bibury Mill access road	Damaged. Requires cleaning. Not visible to cars.
	40/Open limit	Coln Road opposite Bibury Mill access road	Damaged. Requires cleaning. Not visible to cars.
	30	Coln Road opposite Bibury Mill access road	Damaged. Requires cleaning. Not visible to cars.









Photo	Sign	Location	Condition & Recommendation
	30/Children	Coln Road opposite Bibury Mill access road	Very dirty. Black. Not very visible especially the 30 sign. Replace
	30/Children	Coln Road opposite Bibury Mill access road	Very dirty. Black. Not very visible especially the 30 sign. Replace
	Open sign/40.	Coln Road footpath to Aldsworth Road	Obscured by foliage. Faded and non reflective.
	Open sign/40. 'Bibury'	Coln Road footpath to Aldsworth Road	Obscured by foliage. Faded and non reflective.
	Open sign/40. 'Bibury'	Coln Road footpath to Aldsworth Road	Obscured by foliage. Faded and non reflective.
	Open sign/40.	Coln Road footpath to Aldsworth Road	Obscured by foliage. Faded and non reflective.
	Children Crossing	Coln Road footpath to Aldsworth Road	Faded. Replace.
	40	Coln Road footpath to Aldsworth Road	Obscured by overgrowth









Photo	Sign	Location	Condition & Recommendation
	One Way	Cemetery Lane	Good
	No Entry	Cemetery Lane	Good. Requires slight adjustment.
	No Entry	Cemetery Lane	Good. Requires slight adjustment.
	No Through Road. Except for Access	The Square	Good
	One Way	Church Road	Faded. Poor condition. Replace
	One Way	Church Road	Faded. Poor condition. Replace
	7.5 T weight limit. Accept for Access	The Swan	Both signs badly damaged. Replace with new
	7.5 T weight limit. Accept for Access	The Swan	Both signs badly damaged. Replace with new

Photo	Sign	Location	Condition & Recommendation
	7.5 T weight limit. Accept for Access	The Swan	Both signs badly damaged. Replace with new
	7.5 T weight limit. Accept for Access	The Swan	Both signs badly damaged. Replace with new
	7.5 T weight limit. Accept for Access	The Swan	Both signs badly damaged. Replace with new
	Open sign/30	The Swan - Trout Farm carpark	Obscured by overgrowth. Faded. Clean, cut back overgrowth
	Open sign/30	The Swan - Trout Farm carpark	Obscured by overgrowth. Faded. Clean, cut back overgrowth
	Open sign/30	The Swan - Trout Farm carpark	Obscured by overgrowth. Faded. Clean, cut back overgrowth
	Open sign/30	The Swan - Trout Farm carpark	Obscured by overgrowth. Faded. Clean, cut back overgrowth
	No Turning. Heavy Goods Vehicle	Awkward Hill	Remove?









Photo	Sign	Location	Condition & Recommendation
	7.5 T weight limit. Accept for Access	Ablington	Faded to nothing. Replace
	7.5 T weight limit. Accept for Access	Ablington	Faded to nothing. Replace
	Finger Post 3-way	Ablington	Requires a new post & cleaning
	7.5 T weight limit. Accept for Access	Ablington	Good
	7.5 T weight limit. Accept for Access	Ablington	Faded
	'Ablington'	Ablington	Replace with a new sign
	No Through Road	Ablington	Needs uprighting
	Finger Post 3-way	Ablington	Requires cleaning

Photo	Sign	Location	Condition & Recommendation
	7.5 T weight limit. Accept for Access	Ablington	Both completely obscured. Relocate or cut back overgrowth.
	7.5 T weight limit. Accept for Access	Ablington	Both completely obscured. Relocate or cut back overgrowth.
	7.5 T weight limit. Accept for Access	Ablington	Both completely obscured. Relocate or cut back overgrowth.
	7.5 T weight limit. Accept for Access	Ablington	Both completely obscured. Relocate or cut back overgrowth.
	'Ablington'	Ablington	Good. Requires cleaning.
	Finger Post	Ablington	Good. requires cleaning.
	Bend to left	Ablington	Partially obscured. Faded. Replace
	Bend to right	Ablington	Too high to be visible. Obscured. Re-locate.

Photo	Sign	Location	Condition & Recommendation
	7.5 T	Ablington	Faded both sides. Replace
	No Trucks	Ablington	Faded both sides. Replace
	Finger Post with No Trucks	Ablington	Completely obscured from all angles. Faded. Replace. Re-locate. Cut back overgrowth
	Finger Post with No Trucks	Ablington	Completely obscured from all angles. Faded. Replace. Re-locate. Cut back overgrowth
	Finger Post with No Trucks	Ablington	Completely obscured from all angles. Faded. Replace. Re-locate. Cut back overgrowth
	Bend	Ablington	Completely obscured. No longer visible. Re-locate.
	Bend	Ablington	Obscured by overgrowth
	Ablington'	Ablington	Faded. Replace.